

6.1 Chassis or frame and attachments

6.1.1. General condition

Rear / Offside / Inner / Upper

CVRT Test Report YY-CC-12345

TEST RESULT Fail. N.B.! - RE-TEST MUST BE COMPLETED BY "15/05/2018". RE-TEST FEE: €90.81

You should book an appointment for your re-test at least 5 days before 15/05/2018

Please note that all re-tests must be conducted within 21 calendar days and within 4 000kms of the initial full test

entre/Test/Tester Details						
VR Testing centre name	Athlone Institute of Tec	chnology	Unique CVR	Testing Centre nu	mber/ID 7	
VR Testing centre Ph number	090 64 81824	Unique Test I	Unique Test ID number 700011			
ehicle Tester ID		Test date	Test date		10/05/2018	
ehicle/Owner/Presenter De	etails					
egistered Owner's Name	Vehicle	Registration Nu	mber YYCC	12345	Odometer Reading 555	KM
	Manufa	Manufacturer				
egistered wner's Address	Model					
		GDVW (Gross Design Vehicle Weight)				
	VIN Nun					
	Test Car	tegory	Carria	qe > 8 <= 14 pa	ssenger seats	
teering Alignment					Limits	Result
Axle 1 1m/	/km				Outside ±14.00m/km	PASS
rake Test	Brake Effo	rt		Imbalance	Limits	Result
	Nearside	Offside	Design Axle Weight			
ervice Brake Axle 1	5000KGF	5000KGF	4000Kg	0%	Imbalance above 30%	PASS
ervice Brake Axle 2	5000KGF	5000KGF	4500Kg	0%	Imbalance above 30%	PASS
arking Brake Axle 2	5000KGF	5000KGF	4500Kg	0%	Imbalance above 50%	PASS
ervice Brake Efficiency		571.43%			Efficiency Below 55%	PASS
arking Brake Efficiency		285.71%			Efficiency Below 16%	PASS
moke					Limits	Result
	Engine Tem	р	Result			
	1 °C		Opacity (k-mean) 1		Above 3M-1	PASS
eadlamp Aim Testing					Limits	Result
	Nearside	Offside				
Dip Beam	PASS	PASS				PASS
dditional Fail Items/Deficie						Result
		ason	variation in broke effect (obbine\		Coll M-1
BRAKING EQUIPMENT 1.2 Service braking perfo	(e) ormance and efficiency	i No graduai	variation in brake effort (gr	abbing).		Fail Maj
1.2.1: Performance	and and onloiding					
n.z.m. r snomanso	(В	rake Equipme	ent Re-Test Required)			
VISIBILITY	(e)	Windscreer	is not marked as automoti	ve safety glass		Fail Ma
3.2: Condition of glass	(-)			, 3		

Page 1

6	CHASSIS, CAB AND BODYWORK	(c)	Leaks in system are evident.	Fail Majo
	6.1 Chassis or frame and attachments			
	6.1.3 Fuel tank and pipes (including heating	g fuel	tank and pipes)/System	
8	EMISSIONS/NOISE	(a) env	Any excessive fluid leak, other than water, likely to harm the ironment or to pose a safety risk to other road users.	Fail Major
	8.4 Fluid leaks			
	8.4.1. Fluid leaks			
9	SUPPLEMENTARY TESTS FOR PASSENGER-CARRYING VEHICLES M2, M3	(d)	Warning buzzer or lights (where fitted) not working.	Fail Major
	9.1 Doors/Body Condition and Integrity			
	9.1.2. Emergency exits			
	Rear / Offside / Inner / Upper			

Vehicle Reg Number

06C25015

Vehicle Tester ID

761

Test Date

10/05/2018

TEST RESULT

Unique CVR Testing Centre Number/ID

FAIL

THIS VEHICLE HAS MAJOR DEFECTS THAT MAY PREJUDICE ITS SAFETY OR HAVE AN IMPACT ON THE ENVIRONMENT OR PUT OTHER ROAD USERS AT RISK. ALL DEFECTS IDENTIFIED IN THIS REPORT MUST BE RECTIFIED

RE-TEST FEE: €90.81

PLEASE READ CAREFULLY - RE-TEST

RE-TEST MUST BE COMPLETED BY "15/05/2018".

INFORMATION ABOUT RE-TESTS

Please note that all re-tests must be conducted within 21 calendar days and within 4,000Kms of the initial or periodic test.

A re-test can only be conducted at the CVR testing centre where the original test was failed. Where a vehicle is presented for a re-test at another testing centre, a full test must be conducted at a full test price.

Please note all defects identified in this test report (including Minor Deficiencies) must be rectified before presenting the vehicle for a re-test.

A re-test which requires the use of test equipment will incur a fee. It is advised that you make arrangements for your re-tests as soon as possible to allow for the possibility that additional re-tests may need to be conducted within 21 calendar days. The re-test fee is noted above in this report.

The vehicle can be booked in online at www.cvrt.ie or you can phone your CVR testing centre to arrange a suitable date and time.

Re-tests not requiring the use of test equipment will be conducted free of charge but still must be conducted within 4,000kms and 21 calendar days.

Please note that if either type of re-test is sought after 21 calendar days of the initial or periodic test, the CVR testing centre must conduct another full test at a full test price. This is because the condition of the vehicle may have deteriorated in the interim period.

ODOMETER READINGS

The recipient of this Test Report should check that the odometer reading entered on this statement is correct and inform the CVR Test Operator, before leaving the CVR testing centre, if it is not.

Key: N/D = Not Done Fail DD = Fail Dangerous

Note: All Equipment 'Fail' results are categorised as 'Major' unless otherwise specified