



CVRT Test Report YY-CC-1234

TEST RESULT: Pass pending re-check of Minor Deficiencies

IMPORTANT: THIS IS NOT A PASS STATEMENT OR A CERTIFICATE OF ROADWORTHINESS (CRW).

YOU WILL NEED TO HAVE ALL MINOR DEFICIENCIES, IDENTIFIED IN THIS TEST REPORT, RECTIFIED. THE VEHICLE WILL THEN HAVE TO BE RE-CHECKED AT THE SAME TEST CENTRE THAT CARRIED OUT THE INITIAL TEST TO CONFIRM THAT ALL MINOR DEFICIENCIES HAVE BEEN RECTIFIED IN ORDER FOR A PASS STATEMENT TO BE ISSUED AND FOR YOU TO OBTAIN THE CRW.

Further information regarding the re-check is included at the end of this test report.

Centre/Test/Tester Details

CVR Testing centre name	Athlone Institute of Technology	Unique CVR Testing Centre number/ID	7
CVR Testing centre Ph number	090 64 81824	Unique Test ID number	70001114
Vehicle Tester ID		Test date	16/05/2018

Vehicle/Owner/Presenter Details

Registered Owner's Name	Vehicle Registration Number	YYCC1234	Odometer Reading	852 KM
Registered Owner's Address	Manufacturer	MERCEDES BENZ		
	Model			
	GDVW (Gross Design Vehicle Weight)			
	VIN Number			
	Test Category	Goods > 7,500kg 2 Axle		

Steering Alignment

Axle	Unit	Limits	Result
Axle 1	1m/km	Outside ±14.00m/km	PASS

Brake Test

Brake Test	Brake Effort		Design Axle Weight	Imbalance	Limits	Result
	Nearside	Offside				
Service Brake Axle 1	5000KGF	5000KGF	8000Kg	0%	Imbalance above 30%	PASS
Service Brake Axle 2	5000KGF	5000KGF	8000Kg	0%	Imbalance above 30%	PASS
Parking Brake Axle 2	5000KGF	5000KGF	8000Kg	0%	Imbalance above 50%	PASS
Service Brake Efficiency		50.00%			Efficiency Below 50%	PASS
Parking Brake Efficiency		25.00%			Efficiency Below 16%	PASS

Smoke

Engine Temp	Result	Limits	Result
1 °C	Opacity (k-mean) 1	Above 1.5M-1	PASS

Headlamp Aim Testing

Dip Beam	Nearside	Offside	Result
	PASS	PASS	

Additional Fail Items/Deficiencies

Item	Reason	Result
0 IDENTIFICATION OF THE VEHICLE 0.2: Vehicle identification / chassis / serial number	(c) Illegible vehicle documents or clerical inaccuracies.	Minor Deficiency

TEST RESULT

PASS PENDING RECHECK OF MINOR DEFICIENCIES

RE-CHECK FEE : €0.00

PLEASE READ CAREFULLY - RE-CHECK

Unique CVR Testing Centre Number/ID	Vehicle Reg Number	Vehicle Tester ID	Test Date
7	11RN1881	761	16/05/2018

INFORMATION ABOUT RE-CHECKS

Please note that the Certificate of Roadworthiness (CRW) **will not be issued** until all minor deficiencies identified on this report have been rectified and re-checked and verified by the Test Centre who carried out the original test.

A re-check can only be conducted at the CVR testing centre where the original test was carried out. Where a vehicle is presented for a re-check at another testing centre, a full test must be conducted at full test price.

There is no fee for a re-check.

There is no specified time period or mileage limit for the conduct of a re-check, however, any minor deficiencies identified during the initial test should be rectified as soon as possible to ensure that the vehicle is maintained in a roadworthy condition and that a CRW is issued for your vehicle without delay.

Please contact your CVR Test Centre to arrange a suitable date and time for the re-check.

ODOMETER READINGS

The recipient of this Test Report should check that the odometer reading entered on this statement is correct and inform the CVR Test Operator, before leaving the CVR testing centre, if it is not.

Key: N/D = Not Done Fail DD = Fail Dangerous Note: All Equipment 'Fail' results are categorised as 'Major' unless otherwise specified